



19th century north vestry, c1975

One of a series of views taken after the eastern arm of the church was abandoned due to roof defects. The north vestry was built as part of the mid-19th century restoration programme and may have replaced an earlier structure though none is shown on the watercolours of c1810. In 1975 its roof was still in place but continuing lack of maintenance led in the 1980s to its collapse and the capping of three walls. In 2018 the roof was reinstated as part of its conversion to a toilet facility.

EB221 (*Beds CC Photographic Unit, BARS Z50-18-5*)