



Chancel interior c1975 facing north-east

Taken after the chancel was closed and the east window boarded up, with furniture damaged by water through the roof still in place.

EB190 (*Beds CC Photographic Unit BARS Z50-18-7*)