



Subsidence in the raised floor of the Mausoleum 2010 due to inadequate structural compression



Blocking interior wall within Mausoleum revealed by sinkage of poorly compacted fill, 2010



Inspection of used portion of St John Mausoleum by County Archive staff, 2003 – see separate report



Lead coffin in vault of St John Mausoleum: 2003 County Archivist inspection – see separate report