





2010 repairs

Clay-heave cracks in nave walls. (Above) west wall showing cyclical cracks also visible on 1940s pictures; (below) internal view (left) after plaster removal