



2010 nave cracks repairs

Before re-plastering the cracks were filled with soft mortar to allow further movement without greater damage and pins were inserted across the gaps.